

NCG CAM Solutions Ltd are pleased to release NCG CAM v14.0.06

Since we released V14.0.05 there are a handful of little fixes.

Please note that NCG CAM v14.0 will not install on Window XP, and that at some point in the first quarter of 2016 NCG CAM will be available as a 64 bit installer only.

4203 : Shaft Profile: The Shaft profile is now active for transformed toolpaths. Also corrected a problem meaning shaft profile tool data was not being picked up in cutting parameter plans from transformed toolpaths.

4261 : Toolsheets : An option, "Respect new lines in project comments", has been added to the toolsheet macro so that we can honour the new lines in the project comment. The default behaviour is to have the comment all on one line.

4269 : Post processor: Heidenhain: Corrected a problem in the post when using the tool name (not the tool number), and preselecting the next tool.

4276 : UI: Tool Page - Ruler witness lines for Dove, Lollipop & T-Slot cutters was not correct, this has now been fixed.

4291 : Post processor: Heidenhain: Corrected a problem in the drilling that could cause the rapid command to be issued with the retract move on the last hole (it was retracting at the drilling feedrate).

Updated the German Turkish and Korean translations.